

PWS ID: OH4503312

Park constructed late 1960's w/galvanized. Replaced w/plastic (schedule 80 PVC) in 1970's.

Well & lot service lines are polyethylene.

All lines are now plastic. Valves are brass (contain lead) and stainless.

Therefore, possible lead in the plumbing fittings and fixtures does exist. Because it is practically impossible to determine the lead content of an installed fixture, fitting or pipe, it should be assumed that the manufacture or installation date is the primary indicator of the lead content. Therefore, the characteristics of buildings and piping solder or fixtures would be buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than

8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

It is expected that minute amounts of lead may be present in some drinking water samples from anywhere in the park.

WRIGHT TR, FREDERICK W  
FREDERICK W WRIGHT TRUST,  
200408310031590  
TD=8.625

11107

Wilkins Run Rd NE

250

37

FIRST ST NE

94

SECOND ST NE

WRIGHT TR, FREDERICK W  
2000100900321441  
TD=13.517

THIRD ST NE

106

826.58

HYSSELL,

20070131

TD=45