



Lead Service Line and Fixture Map for Honda Marysville Campus

Date of Drawing: 1-12-2017

MAP2 PbCu2-C.dwg File Name: HAM FAC_ENV Generated by:

NOTES

Ohio House Bill 512 Drawing

OH8035512 PWS ID:

PWS Name: Honda-Benton Road Water Plant

Address: 20001 Johnson Road

Raymond, Ohio 43067

(937) 246-4802 Phone:



Spreadsheet for lead and copper sample sites

* = Required field					
PWS ID*	PWS Name*	SMP ID*	Tap Location*	Plumbing Age*	Type of Interior Plumbing
OH8035512	Honda-Benton Road Water Plant	LC201	HHC Café Sink	CuPb>82	Copper
OH8035512	Honda-Benton Road Water Plant	LC202	Drinking Fountain @ Column F27	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC203	Drinking Fountain @ Column FF18	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC204	Drinking Fountain @ Column I17	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC205	East Locker Room Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC206	FTZ Gate House Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC207	MMC Café Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC208	Gate A Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC209	MMC Locker Room Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC210	PMC - Lunchroom Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC211	North Café Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC212	Rest Room Sink @Column DD60	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC213	South Locker Room Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC214	TRC Bldg. 10 Men's RR Left Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC215	TRC Bldg. 20 Women's RR Left Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC216	TRC Bldg. 40 Men's RR Left Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC217	TRC Bldg. 50 Men's RR Left Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC218	TRC Bldg. 60 Men's RR Left Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC219	West Cafeteria Sink	CuPb<83	Copper
OH8035512	Honda-Benton Road Water Plant	LC220	West Locker Room Sink	CuPb<83	Copper

• Ductile Iron - Type of Pipe Material at this location in the main distribution



• Ductile Iron - Type of Pipe Material at this location in the main distribution



• Poly PVC - Type of Pipe Material at this location in the main

distribution



• Ductile Iron - Type of Pipe Material at this location in the main

distribution



• Ductile Iron - Type of Pipe Material at this location in the main

distribution

