



RECEIVED
OHIO EPA

MAR 06 2017

Southwest District



**McMAHAN'S
FAIRWAY TERRACE**

12250 Lower Valley Pike
Medway, Ohio 45341
937-878-3107
Fax 937-878-3023



Fairway Terrace Mobile Home Park is community water system to public lots. Our park was built in 1968. Our water lines consist of 4" ductile 4" plastic, 2" plastic and 2" galvanized piping. There is also some 3/4" plastic and 3/4" galvanized lines run into some lots as lateral. In the water crocks on each lot there is 3/4" lines as riser with a 3/4" brass valve with a brass or plastic water meter. There is also some 4" ductile and 2" brass valves throughout the park. On the main lines to isolate different lines. To the best of our knowledge, All the maintenance work we have done, We have no lead lines in your system.

Because it is practically impossible to determine the lead content of an installed fixture, fitting or pipe, it should be assumed that the manufacture or installation date is the primary indicator of the lead content. Therefore, the characteristics of the buildings and piping solder or fixtures would be buildings built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead. 27-Feb-17 materials manufactured after 1998. In addition, building built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

Respectfully,

Servy Mc Mahan Pres 3/3/17

RECEIVED
OHIO EPA

MAR 06 2017

VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS CLAIMING NO LEAD SERVICE LINES

South District

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

LEAD SERVICE LINE VERIFICATION	
This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):	
<input type="checkbox"/>	Historical permit records and/or local ordinances
<input checked="" type="checkbox"/>	Distribution maintenance records (i.e. meter replacement, waterline break repairs)
<input type="checkbox"/>	Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)
<input type="checkbox"/>	Service line material of all service lines is known (i.e. all service lines are known to be PVC)

Jerry McMahon 3/3/17
 Signature of Responsible Person Date

Jerry McMahon Pros
 Printed Name and Title of Responsible Person

Jarway Seware
 PWS NAME: M.P.H.
 PWS ID: OH 1202312
 COUNTY: CLARK

For Ohio EPA use only:
Date Verification Rec'd: _____

Fairway Terrace MHP

Shade sites are
the sample sites

RECEIVED
OHIO EPA
MAR 06 2017
Southwest District

