



Imagery ©2018 Google, Map data ©2018 Google 50 ft

Legend = PVC/Plastic

Narratives:

Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

PWS Name ASHANTON DAYCARE

Reviewer Amy Smith

PWS ID OH7136514

Review Date _____

REVIEW CHECKLIST FOR 6109.121(F) LCR MAPPING

Due Date	3/9/2017
Received Date	Submittal Complete <input type="checkbox"/> Yes <input type="checkbox"/> No
NOD Date	
Revision Receipt Date	Submittal Complete <input type="checkbox"/> Yes <input type="checkbox"/> No
Review Completion Date	

Mapping in Distribution Systems

- Map(s) of the distribution system
 - Identify major streets, landmarks, bodies of water, or other methods of orientation
 - Areas that are known or likely to have lead service lines are easily differentiated
 - PWS states they have no LSL must provide the following type of documentation and a completed verification form
 - review of historical permit records and/or local ordinances
 - distribution maintenance records (i.e. meter replacements, waterline break repairs)
 - that all service lines were installed after 1986 when LSLs were banned.
- Narrative description of buildings served by the water system likely to contain lead solder, plumbing or fixtures.
- Provide LCR sampling locations – do not have to be shown on map

Mapping for Individual Buildings

- Map(s) of the building distribution system
 - Identify areas that may contain lead piping, solder, or fixtures
- Identify system pipe materials, locations, and date of installation
- Provide LCR sampling locations – do not have to be shown on map

Comments: CUSTOMER SAID POLE BUILDING WAS BUILT IN 1989 AN ONLY PVC
WATER LINES WERE USED.

HOUSE WAS BUILT IN 1923. BETWEEN 1986/1987 ALL PLUMBING WAS REPAIRED
WITH PVC