Hubbard, Ohio

Red - High possibility of lead service connection

Green - Moderate possibility of lead service connection

Yellow - Slight chande of lead service connection

Orange - Virturally no possibility of lead service connection

Buildings built prior to 1988 or that use plumbing material or solder manufactured before 1988 may have materials with greater than 8% lead and are at a higher risk of contributing to lead in the drinking water than materials manufactured after 1988. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than .2% lead by weight and have the lowest risk for contributing lead to the drinking water, It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.