

RE: Huron City
Report
Drinking Water Program
Erie County
PWS ID: OH2201011

CITY OF HURON WATER DISTRIBUTION SYSTEM MAP LEAD MAPPING

Lead pipes built prior to 1975 or that use plumbing material or solder manufactured before 1978 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than material manufactured after 1978. In addition, building code of plumbing material manufactured after 2014 were required to have less than 0.2% lead by weight and have the lowest risk of contributing lead to the drinking water. It should be noted however that although prohibited, some use of leaded solder or leaded components has been observed during inspections for lead service lines.

Upon opening in an old or system map you will notice some areas of red color indicating water mains that may contain lead service lines. The City of Huron has no known lead service lines at this time. Linking the age of water mains to be used as records of past lead service lines we identified the below areas in red color as potentially containing lead service lines. It has been the policy of the City of Huron to eliminate any and all lead service lines upon renovation and thus we have no known lines at this time. An overview of lead piping will be found in the report of this project.



- LEGEND**
- WATER MAIN
 - ABANDONED WATER MAIN
 - METER
 - VALVE
 - △ REDUCER
 - ⊕ FIRE HYDRANT



RECEIVED
FEB 10 2017
DDAGW - NWDO