Cardington Lincoln High School PWS # OH5942713 Facility ID: DSI Class I Non-transient / Non-Community 121 Nichols St. Cardington, OH 43315

John Nippert, Maintenance (614) 207-8080

The complex has been built in multiple phases. The time period of each phase is as follows:

Phase one (1) – Zones D & G - Constructed pre-1965 Phase two (2) – Zones A, B, & C - Constructed 2005

Therefore, possible lead in the plumbing fittings and fixtures does exist. Because it is practically impossible to determine the lead content of an installed fixture, fitting or pipe, it should be assumed that the manufacture or installation date is the primary indicator of the lead content. Therefore, the characteristics of buildings and piping solder or fixtures would be buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

The service line is copper from the road to the building. The Village of Cardington (PWS# OH5900112) supplies the water. The distribution system consists of approximately 95% copper and 5% plastic water lines. The original water lines were installed prior to 1998. Since Zones A, B,& C were constructed after 1998, but before 2014, therefore, there is no more than 8% lead in the plumbing fittings and fixtures.

Operator of Record: Michael Fry (419) 560-0384 Danny Wood (419) 768-1584

