

RE: McDonalds Restaurant - Bellville  
Report  
Drinking Water Program  
Richland County  
PWS ID: OH7048312

Craig Roberts

Operator Cert. # WS1-1013698-89

Here is the map for McDonlds Bellville and Hanley Road. Some of the hot water has soldered joints but was in long before the decision was made to reduce lead solder. We have had no lead show up in the water for either McDonlds. We take five samples from all the sinks in the resauarnt and have no lead show up.

" building in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective."


Craig Roberts

**RECEIVED**

**MAR 06 2017**

**OHIO E.P.A.  
N.W.D.O.**

# BELLVILLE McDonald's



PWS ID 7048312  
860 ST Rt 97 BELLVILLE OH  
LINES: PLS, CU,  
HOT WATER HAS SOLDERED JOINTS  
SOLDERED JOINT CONTAIN LEAD

**VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS  
CLAIMING NO LEAD SERVICE LINES**

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

LEAD SERVICE LINE VERIFICATION
<p><b>This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):</b></p> <ul style="list-style-type: none"> <li><input type="checkbox"/> Historical permit records and/or local ordinances</li> <li><input type="checkbox"/> Distribution maintenance records (i.e. meter replacement, waterline break repairs)</li> <li><input type="checkbox"/> Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)</li> <li><input type="checkbox"/> Service line material of all service lines is known (i.e. all service lines are known to be PVC)</li> </ul>

**RECEIVED**

MAR 06 2017

OHIO E.P.A.  
N.W.D.O.

	<p><b>PWS NAME:</b> <u>McDonalds BELLVILLE</u></p> <p><b>PWS ID:</b> <u>OH 7048312</u></p> <p><b>COUNTY:</b> <u>Richland</u></p>
<p>Signature of Responsible Person Date <u><i>[Signature]</i></u></p>	<p><u>3/3/2017</u></p>

CRAIG ROBERTS	3/3/2017
Printed Name and Title of Responsible Person	

Lead Mapping Verification Form Revised 2/14/17

**For Ohio EPA use only:**

Date Verification Rec'd: \_\_\_\_\_