

Lead Mapping
Travel Centers of America # 39
Hebron, Ohio
PWSID # OH 4544512



Lead Mapping In Distribution System

Travel Centers Of America #39

10679 Lancaster Road

Hebron, Ohio

PWSID # OH 4544512



Lead Service Lines: The Travel Center in Hebron, Ohio consists of three restaurants, a convenience store, rest rooms, and showers. The treatment of the well water is accomplished with iron removal using aeration and oxidation, ion exchange, and disinfection. Chemicals include salt, and chlorine. At the well water treatment building no lead service lines are present according to Matt Waspe with Clear Water Solutions, who has done recent maintenance to the treatment train. From talking with John Barret maintenance supervisor, he recently conducted an audit and reported back to me that no lead service lines are in the ground or inside of the facility. The good thing about Travel Centers # 39 is they have made updates to most of the plumbing in the facility. The large restaurant is currently under construction replacing all of the existing plumbing. The other two restaurants will be updated this year, but have made plumbing improvements in 2007. In general, all plumbing in the facility falls under two categories:

1. After 2014- Least likely lead in solder.
2. 1998-2014- Less likely lead in solder.

Plumbing Solder, Fixtures: From meeting and talking with John Barret maintenance supervisor at the Travel Centers of America # 39 Hebron Location, all piping consists of copper, galvanized, and polyethylene 5100 200 psi copper type size plastic pipe. Fixtures have all been updated and fall within the two categories, as stated previously.

The Following Results:

5 samples June 2005 Lead Copper- No Violations

5 samples June 2008 Lead Copper- No Violations

5 samples June 2011 Lead Copper- No Violations

5 samples June 2014 Lead Copper- No Violations

Respectfully,

John Geller

Operator of Record

Travel Centers of America # 39

Osterfeld, Dan

From: John Geller <jgeller@heathohio.gov>
Sent: Friday, March 03, 2017 3:47 PM
To: Osterfeld, Dan
Subject: RE: Pb Map for Travel Centers of America 39

Dan,
On the first page it specifically says under the heading **Lead service lines** From talking with John Barret maintenance supervisor, he recently conducted an audit and reported back to me that no lead service lines are in the ground or inside of the facility. On the second page it says under **Plumbing solder, fixtures** Travel centers of America # 39 Hebron location, all piping consists of copper, galvanized, and polyethylene 5100 200 psi copper type size plastic. **The line running from the well to the building is copper.** I can specifically point that out on the map and make that statement if you feel it is necessary. I go into surgery Monday for a knee replacement so it would probably be later in the month for a response.

Thanks ,

J. Geller

From: dan.osterfeld@epa.ohio.gov [mailto:dan.osterfeld@epa.ohio.gov]
Sent: Friday, March 03, 2017 3:20 PM
To: jgeller@heathohio.gov
Subject: Pb Map for Travel Centers of America 39

John:

I reviewed the Pb mapping info that you submitted and was received yesterday. One comment that needs to be addressed is that you need to include info on the service line from the well/treatment building to the main buildings/restaurant. It is not shown on the map and there is no statement in the narrative as to what the pipe material is and the date of installation.

At this point, my suggestion is to add a sentence or two to the narrative that specifically addresses both the well and the pipe material from the treatment building to the main buildings, including dates of installation, if known. Then submit this to me as an attachment.

Contact me if you have questions. I am leaving shortly today, but will be in all day Monday and Tuesday.

Regards,

Dan Osterfeld
Ohio EPA, Central District Office
Division of Drinking and Ground Water
50 West Town Street
Columbus, Ohio 43215
(614) 728-5034
dan.osterfeld@epa.ohio.gov

