

# VILLAGE OF MINGO JUNCTION JEFFERSON COUNTY, OHIO



Of the 1645 structures in the Mingo Junction water distribution system all but 3 were built prior to 2014 and may have materials greater than 8% lead and are at a higher risk of contributing lead to drinking water than materials manufactured after 2014. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions become effective.

- Colors**
- Lead = ■
  - Non-Lead = ■
  - No Information = ■
  - TIER 1 SITES = ●

ALL STRUCTURES CONNECTED TO THE VILLAGE OF MINGO WATER DISTRIBUTION SYSTEM, DESIGNATED BY YELLOW, MAY HAVE POTENTIAL LEAD MATERIAL CONTENTS EITHER IN THE SERVICE TO THE STRUCTURE, INTERIOR PLUMBING OR FIXTURES.

2017 MAR - 8 PM 12



# VILLAGE OF MINGO JUNCTION JEFFERSON COUNTY, OHIO



Of the 1645 structures in the Mingo Junction water distribution system all but 3 were built prior to 2014 and may have materials greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 2014. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions become effective.

- Colors
- Lead = ■
  - Non-lead = ■
  - No Information =
  - TIER 2 SITES = ●

ALL STRUCTURES CONNECTED TO THE VILLAGE OF MINGO WATER DISTRIBUTION SYSTEM DESIGNATED BY YELLOW MAY HAVE POTENTIAL LEAD MAY OR MAY NOT BE IN THE STRUCTURE OR PLUMBING OR FITTINGS

2017 MAR -8 PM 12:00  
 8 7 11