

# Village of Freeport

P.O. Box 176, Freeport, Ohio 43973

Village of Freeport Lead Mapping Narrative PWS ID# OH3400212<sup>4</sup>

Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.05% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however, that although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

Buildings within the Village of Freeport have nearly exclusively been built prior to 1950. A few exceptions include manufactured homes. Therefore, it is assumed that most of our homes could have interior plumbing and/or fixtures that could contain lead. All water mains within the Village were replaced in 1991. All public sides of the service connections were replaced with brass collars and plastic or copper. It is not known what type of material makes up the private side of the service line.


2017


# Freeport

OH 3400412



 = TIER I  
SAMPLE SITES

 = NON-LEAD SERVICE  
CONNECTIONS

 = UNKNOWN LEAD CONTENT  
PRIVATE SIDE  
SERVICE LINES