

Phone 740,869,2040

Fax 740.869.9010

Galbreath Square 1 South London Street Mt. Sterling, OH 43143

> Ohio EPA/CDO 50 W. Town St., Suite 700 Columbus, OH 43216

ATTN: Drinking Water

Subject: Lead Service Line and Fixture Mapping Project – PWS ID: OH4900812

Greetings:

As requested, please find several documents regarding the drinking water supply system for the Village of Mount Sterling, Ohio. We are not aware of any lead service lines in the village. Most of the supply lines in the village were replaced with C-900 line during several major projects over the past 10-15 years.

The SMP ID reports have indicated no lead or copper in the sites sampled. We have mapped out (map included) residential facilities in the village to indicate dates of construction per the Madison County Auditor's records. Clearly, the manufacturing and installation dates of piping and fixtures in residences will be the primary indicator of possible lead and copper content. Buildings in Ohio built prior to 1998 or that use plumbing materials or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufacture after 1998. In addition, building constructed and materials manufactured after 2014 were required to have less than 0.25% lead by weight and have a lower risk of contributing lead to the drinking water. It should be noted however, that although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

If we may provide additional information or amplification of any included herein, please call.

Sincerely.

John R. Martin

(Village Administrator

740-869-2040 / EXT 112



VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS CLAIMING NO LEAD SERVICE LINES

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following): Historical permit records and/or local ordinances Distribution maintenance records (i.e. meter replacement, waterline break repairs) Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned) Service line material of all service lines is known (i.e. all service lines are known to be PVC)

John R. Martin	3/10/1-1		
Signature of Responsible Person	Date		HT. STERLING
USDAN MARTIN VILLAG	ADMINISTRATOR	PWS ID:	0H4900312
Printed Name and Title of Responsible Person			1 11 12 20 101

Por Ohio EPA use only:

Date Verification Rec'd:

3/10/17