RE:

HOLGATE VILLAGE Report Drinking Water Program Henry County PWS ID: OH3500512





## RECEIVED

MAR 08 2017

DDAGW - NWDO

March 8, 2017

Via Email: Lara.Schramm@epa.ohio.gov

Ms. Lara Schramm Ohio EPA Northwest District Office Division of Drinking and Ground Waters 347 North Dunbridge Road Bowling Green, Ohio 43402

Re: HB-512 Lead and Copper Map Updates

> Holgate, Ohio PWS# OH3500512

PDG Job No. 129200-00022

Dear Ms. Schramm:

Enclosed, please find the following items for your review and approval for compliance with HB-512 Lead and Copper Mapping.

- 1. An updated distribution map of the Village of Holgate water distribution system.
- 2. Summary Report of the Village's distribution system and structures within the Village served by the water system.
- List of Tier 1 Site and addresses that are currently used to test for lead and copper.

All information herein has been obtained from the Village of Holgate, compiled by PDG, and reviewed by all parties. This information is to the best of our knowledge complete and accurate given the information and documentation available to all parties at this time.

If you have any comments or need additional information, please don't hesitate to contact this office or the Village of Holgate.

POGGEMEYER DESIGN GROUP, INC.

Lee P. Rausch, P.E. Sr. Project Manager

Dan Davis, Holgate Village Administrator CC:

Ohio Department of Health

Ohio Department of Job and Family Services

Enclosures: 24" x 36" Map

**Summary Report** Tier 1 Sites



M

RECEIVED

Village of Holgate Distribution System Lead & Copper Mapping HB - 512 PWS # OH3500512

MAR 08 2017

DDAGW - NWDO



Village of Holgate, Ohio Henry County PWS# OH3500512 MAR 08 2017 DDAGW - NWDO

## **NARRATIVE for 2017 LEAD MAPPING**

**Distribution System Mains:** After review of the Village distribution system as-builts, mapping and various other records available to current Village personnel as well as past operational efforts revealing mainline construction materials, the Village doesn't believe to have mains containing molten leaded joints.

**Service Line Material:** No tap records exist for individual service lines detailing service line materials. It is believed that the majority of service lines in the Village are copper/plastic up to the public R/W. Where cast iron main lines are located, leaded "goosenecks" on the individual service lines may exist, however the location and presence of these is unknown.

**Buildings served by PWS likely to contain lead solder, plumbing or fixtures:** The map submitted details by parcel, homes and buildings built within the specified time frames. Those structures built within the timeframes determined to have the potential of lead solder, plumbing or fixtures beyond the service lateral are detailed based on structure age information obtained from the Henry County Auditors office and local knowledge of the Village.

**Description of areas of the PWSD where susceptible buildings are located:** Buildings that may or may not have lead solder, fixtures or plumbing are located in most of the service area of the Village.

**History of Lead Sampling:** Review of historical data shows that the Village has been below the Action level for lead and copper sampling over the past several years.

Lead and Copper Sample Sites: A listing of Tier 1 sample sites, complete with addresses and contact information is attached.