

## Linda Mobile Home Park Lead and Copper Narrative

The Linda Mobile Park consists of 2 mobile home parks served by 2 wells located in Linda Mobile Park. Airway Mobile Home Park water distribution was constructed in the early 50's while Linda Mobile Home Park water distribution was constructed in the early 70's. There are no records of Airway and Linda Mobile Home Park of what kind of piping materials that were installed in the distribution system but have found galvanized and PVC piping during water main leaks. There hasn't been any lead piping found in the past. Both mobile home parks do have copper and plastic service lines coming from the main to the mobile home. There will be a potential for lead in the distribution system due to brass fittings being installed before 2014. All mobile homes in both parks were all constructed before 2014 and also have lead potential in the plumbing fixtures. Any trailer constructed in or before 1998 could have a lead potential greater than 8 percent while any mobile home constructed from 1999 to 2013 could have lead potential less than 8 percent and any mobile home constructed in 2014 could have a lead potential less than .25 percent.

Jamie Cook

Operator of Record

**VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS  
CLAIMING NO LEAD SERVICE LINES**

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

<b>LEAD SERVICE LINE VERIFICATION</b>
<p><b>This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):</b></p> <ul style="list-style-type: none"> <li><input type="checkbox"/> Historical permit records and/or local ordinances</li> <li><input checked="" type="checkbox"/> Distribution maintenance records (i.e. meter replacement, waterline break repairs)</li> <li><input type="checkbox"/> Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)</li> <li><input type="checkbox"/> Service line material of all service lines is known (i.e. all service lines are known to be PVC)</li> </ul>

<u>James Cook</u>	3.9.17
Signature of Responsible Person	Date
James Cook Operator of Record	
Printed Name and Title of Responsible Person	

**PWS NAME:** Linda Mobile Home Park  
**PWS ID:** OH 0901412  
**COUNTY:** Butler

<p><b>For Ohio EPA use only:</b></p> <p>Date Verification Rec'd: _____</p>
--

# AIRWAY MOBILE HOME PARK

COUNTY OF BUTLER, OHIO

STATE ROUTE 127

FIELD

— Constructed  
 In or Before 1996  
— Empty lots



