


H.B. 512 Service & Fixture Mapping
Lawrenceville Village PWS

Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8" lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.


Clark County Department of Utilities has no records of lead service lines being installed or discovered in any of our service areas. Clark County Department of Utilities has never found a lead service in any of our districts during any meter replacement project, curb valve replacement, water main repair or any other maintenance or replacement activity, however it is possible lead services exist. If a lead service were to be located by Clark County Utilities on the public side of the curb stop, the public side of the service would be removed and replaced by Clark County Utilities. If a lead service were to be located by Clark County Utilities on the private side of the curb stop, the homeowner would be notified that a lead service was located on the private side.



Legend

H.B. 512 Service & Fixture Mapping

- No Service
- Prior to Jan 1, 1998
- Jan 1, 1998 to Jan 1, 2014
- After Jan 1, 2014



Lawrenceville Water System – OH1202812

The Lawrenceville water system serves approximately 110 accounts. Clark County Utilities purchases water from the Village of North Hampton, no additional treatment is provided. The water system began construction in the late 1940's. The system was replaced in 2009 with Ductile Iron Pipe and Copper services on the Utility side of the meter pits. Residents were responsible for running services from their existing services or replacing their existing services.

The service materials in the Lawrenceville system have been found to be copper, HDPE, PEX, cross linked polyethylene, and galvanized steel. No lead services have ever been located by the Clark County Staff during normal maintenance activities or repairs however it is possible lead services exist. If a lead service were to be located by Clark County Utilities on the public side of the curb stop, the public side of the service would be removed and replaced by Clark County Utilities. If a lead service were to be located by Clark County Utilities on the private side of the curb stop, the homeowner would be notified that a lead service was located on the private side.