

B1

A1

B1

B2

C1


C2

ROBIN GRAYS
PWS →


NEW RICHMOND
PWS →

Ohio River

Robin Grays PWS (1 of 2)
Non-Lead
(Possible Lead Components)
Lead Likely



Village Limits



Property Lines



New Richmond Grid

A1

B1

B2

C1

C2

C3



ROBIN GRAYS
PWS

NEW RICHMOND
PWS

Robin-
Grays PWS

Non-Lead
(Possible Lead
Component)

Lead
Likely

Robin Grays PWS Map Distribution System Narrative

Initial construction of homes in the Robin Hill - Grays Lane neighborhood began in the late 1950s. Construction has continued up to the present day. The neighborhood was annexed into the Village of New Richmond *circa* 1969. Up until the year 2000 these homes were serviced by the New Richmond PWS. The Robin Grays PWS was established shortly thereafter. A connection to the Clermont County PUB water plant was made and the village began and continues to this day to purchase water from Clermont County to service the Robin Grays PWS. The current service lines are a combination of copper and 200 psi $\frac{3}{4}$ " plastic. This information is derived from knowledge gathered during water main breaks and service line repairs.

Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective. Most homes in the Robin Grays PWS were built prior to 1998; therefore, it is highly likely that these homes contain components that contain greater than 8% lead components. Two homes have been built subsequent to the 1998 lead requirements.

Robin Grays PWS Map Distribution System Narrative

Initial construction of homes in the Robin Hill - Grays Lane neighborhood began in the late 1950s. Construction has continued up to the present day. The neighborhood was annexed into the Village of New Richmond *circa* 1969. Up until the year 2000 these homes were serviced by the New Richmond PWS. The Robin Grays PWS was established shortly thereafter. A connection to the Clermont County PUB water plant was made and the village began and continues to this day to purchase water from Clermont County to service the Robin Grays PWS. The current service lines are a combination of copper and 200 psi $\frac{3}{4}$ " plastic. This information is derived from knowledge gathered during water main breaks and service line repairs.

VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS CLAIMING NO LEAD SERVICE LINES

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

LEAD SERVICE LINE VERIFICATION

This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):

- ☐ Historical permit records and/or local ordinances
- ☒ Distribution maintenance records (i.e. meter replacement, waterline break repairs)
- ☐ Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)
- ☐ Service line material of all service lines is known (i.e. all service lines are known to be PVC)



Signature of Responsible Person

3/6/2017

Date

Greg Boernts Village Administrator

Printed Name and Title of Responsible Person

PWS NAME:

Robin Grays
PWS

PWS ID:

OH 1330912

COUNTY:

Clermont

For Ohio EPA use only:

Date Verification Rec'd: _____