RE: Northwestern W and SD - Fostoria North

Report
Lead Mapping
Drinking Water Program
Wood County
PWS ID: OH8752712

Northwestern Water & Sewer District

## PWSID 0H8752712 Fostoria North

To the best of the owners' knowledge there are no known lead service lines in the system. This system was constructed in 2000 using C-900 waterline. Based upon tap records all service connections consist of ductile iron, copper, or HDPE material.

RECEIVED

MAR 06 2017

DDAGW - NWDO

## VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS CLAIMING NO LEAD SERVICE LINES

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

## LEAD SERVICE LINE VERIFICATION

This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):

- If Historical permit records and/or local ordinances
- Distribution maintenance records (i.e. meter replacement, waterline break repairs)
- ☐ Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)
- ☐ Service line material of all service lines is known (i.e. all service lines are known to be PVC)

- Wand lickery	3/1/12		
Signature of Responsible Person Date		PWS NAME: Fostonia North	
Dan wickord, Superlute	indent	PWS ID: COUNTY:	0H8752712
Printed Name and Title of Responsible		COUNTY,	W004

For Ohio EPA use only:	
Date Verification Rec'd:	

MAR 06 2017 DDAGW - NWDO

## Potential Lead Services and Water Distribution Lines PWS OH8752712

Non-Single Family Homes Built between 1982-1998

- Distribution Lines

Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In Addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted that although prothibled, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.



