

RE: Northwestern W and SD - Weston
Report
Lead Mapping
Drinking Water Program
Wood County
PWS ID: OH8703211

PWSID OH8703211 Weston





To the best of the owners' knowledge and review of historical permits and maintenance records there are no known lead services in this system. All service connections and service lines have been constructed of copper, galvanized steel or HDPE materials.

RECEIVED

MAR 06 2017

DDAGW - NWDO

**Potential Lead Services and
Water Distribution Lines
PWS OH8703211**

-  Single Family Homes Built between 1982-1998
-  Non-Single Family Homes Built between 1982-1998
-  Single Family Homes Built 1982-Earlier
-  Distribution Lines

Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In Addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

