Northwestern W and SD-Middleton Twp Report Lead Mapping Drinking Water Program Wood County PWS ID: OH8752212 RE:

Northwestern Water & Sewer District

PWSID OH8752212 Middleton Township

To the best of the owners' knowledge along with the review of tap permits and maintenance records there are no known lead service connections in this system. Waterline construction is made of asbestos cement and C-900 material. All service connections are made of copper or HDPE materials.

RECEIVED

MAR 06 2017

DDAGW - NWDO

VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS CLAIMING NO LEAD SERVICE LINES

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

LEAD SERVICE LINE VERIFICATION

This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):

- Historical permit records and/or local ordinances
- Distribution maintenance records (i.e. meter replacement, waterline break repairs)
- ☐ Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)
- ☐ Service line material of all service lines is known (i.e. all service lines are known to be PVC)

Mark lichard	3/1)17	
Signature of Responsible Person	Date	PWS NAME: Middleton Township
Printed Name and Title of Responsible Person		PWS ID: OH 8752212 COUNTY: Wood.

For Ohio EPA use only:	
Date Verification Rec'd:	

MAR 0 6 2017 DDAGW - NWDO

Lead Mapping Verification Form Revised 2/14/17

Potential Lead Services and Water Distribution Lines PWS OH8752212

Single Family Homes Built 1982-Earlier

Non-Single Family Homes Built between 1982-1998

Single Family Homes Built 1982-Earlier

- Distribution Lines

Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher trisk of contributing lead to the drinking water than materials manufactured after 1998. In Addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted that, although prohibited, some use of leaded soider or leaded components may have occurred after the prohibitions became effective.



