

RE: Northwestern W and SD - Portage
Report
Lead Mapping
Drinking Water Program
Wood County
PWS ID: OH8704103

PWSID OH8704103 **Portage**





To the best of the owners' knowledge there are no known lead service lines in this system. Based upon historical tap permits and maintenance records all waterline construction material was asbestos cement, ductile iron, C-900 and HDPE pipe. Based on historical permits and maintenance records, all service connections and taps are made of copper. Customer service lines are copper or HDPE pipe material.

RECEIVED

MAR 06 2017

DDAGW - NWDO

**Potential Lead Services and
Water Distribution Lines
PWS OH8704103**

-  Single Family Homes Built between 1982-1998
-  Non-Single Family Homes Built between 1982-1998
-  Single Family Homes Built 1982-Earlier
-  Distribution Lines

Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

