

RE: Hicksville Village
Report
Lead Mapping
Drinking Water Program
Defiance County
PWS ID: OH2000212

April 24, 2017

The Village of Hicksville Water Department is aware of one (1) lead service line attached to the Village's water system. That service supplies 614 E. High St. It has always been a part of our Lead & Copper sampling routine group, and it has always tested below the Action Level.

Based on the age of the water system, it would be natural to assume there may be more lead service lines however; none have been located or verified to date.

Our routine and back-up sampling locations are concentrated on the older parts of the water system infrastructure that have the potential for lead joints and/or fittings.

"Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective."

Jessica Elson
Water Superintendent
Village of Hicksville
419.542.8984
HixWater@defnet.com



LEGEND

- 12" MAIN
 - 10" MAIN
 - 8" MAIN
 - 6" MAIN
 - 4" MAIN OR LESS
 - FIRE HYDRANT
 - FIRE HYDRANT NUMBER
 - VALVE
 - VALVE NUMBER
- LAST HYDRANT #'s USED - 1157
 LAST VALVE #'s USED - 305

HICKSVILLE, OHIO

WATER DISTRIBUTION MAP
 PROGRAMMER DESIGN GROUP, INC.

APRIL 1992
 REVISED FEBRUARY 1994
 FEBRUARY 1995
 FEBRUARY 1999
 APRIL 2004
 AUGUST 2011