

Dear Sirs,

According to our records The Village of Burton has no lead service lines. The 1994 Lead monitoring report states lead lines were replaced. Burton Village performed a meter replacement starting in approximately 2012 and there was no mention of lead lines reported.

Burton Village has had some new homes built since 1997. Three subdivisions and 12 new homes. The subdivisions are Indian Ridge, Umberfield and Shannon court.

---

Because it is practically impossible to determine the lead content of an installed fixture, fitting or pipe, it should be assumed that the manufacture or installation date is the primary indicator of the lead content. Therefore, the characteristics of buildings and piping solder or fixtures would be buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

**RECEIVED**  
MAR 15 2017

BY: .....


**VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS  
CLAIMING NO LEAD SERVICE LINES**

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

<b>LEAD SERVICE LINE VERIFICATION</b>	
<p><b>This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):</b></p> <ul style="list-style-type: none"><li><input checked="" type="checkbox"/> Historical permit records and/or local ordinances</li><li><input type="checkbox"/> Distribution maintenance records (i.e. meter replacement, waterline break repairs)</li><li><input type="checkbox"/> Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)</li><li><input type="checkbox"/> Service line material of all service lines is known (i.e. all service lines are known to be PVC)</li></ul>	

 _____ Signature of Responsible Person	3-15-17 _____ Date
Paul EATON OPERATOR _____ Printed Name and Title of Responsible Person	

PWS NAME: Buxton water Supply  
PWS ID: OH2800312  
COUNTY: Geauga

<p><b>For Ohio EPA use only:</b></p> <p>Date Verification Rec'd: _____</p>
--

RECEIVED

MAR 15 2017

BY: .....

RECEIVED

FEB 10 2017

Dear Sirs,

OHIO EPA NEDO

According to our records The Village of Burton has no lead service lines. The 1994 Lead monitoring report states lead lines were replaced. Burton Village performed a meter replacement starting in approximately 2012 and there was no mention of lead lines reported.

Burton Village has had some new homes built since 1997. Three subdivisions and 12 new homes. The subdivisions are Indian Ridge, Umberfield and Shannon court.

Entity: Burton Village  
Doc Type: Report  
Doc Subtype: \_\_\_\_\_  
Program: DPAGW  
County: Crawford  
Secondary ID: OH 2800312  
done in color

# PROPERTY MAP VILLAGE OF BURTON



**HESS & ASSOCIATES ENGINEERING, INC.**  
12121 Kinsman Road, Newbury, Ohio 44065  
Tel (440) 564-8008 Fax (440) 564-8176

General Note:  
ALL INFORMATION WAS TAKEN FROM  
GEAUGA COUNTY GIS.

HESS & ASSOCIATES ENGINEERING, INC.  
DOES NOT GUARANTEE THE COMPLETENESS  
NOR ACCURACY THEREOF.

