

VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS CLAIMING NO LEAD SERVICE LINES

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

LEAD SERVICE LINE VERIFICATION	
This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):	
<input type="checkbox"/>	Historical permit records and/or local ordinances
<input type="checkbox"/>	Distribution maintenance records (i.e. meter replacement, waterline break repairs)
<input type="checkbox"/>	Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)
<input checked="" type="checkbox"/>	Service line material of all service lines is known (i.e. all service lines are known to be PVC) - <u>COPPER</u>

Paul R. Warren 7-22-17
 Signature of Responsible Person Date
PAUL R. WARREN DIRECTOR ENVIRONMENTAL SERVICES
WINDSOR HOUSE, TX.
 Printed Name and Title of Responsible Person
CA-1106699-07

PWS NAME: ST. MARY'S ALZHEIMER'S CENTER
 PWS ID: OH 5003012
 COUNTY: COLUMBIANA Mahanoy


RECEIVED
 JUL 24 2017
 BY: _____

For Ohio EPA use only:
 Date Verification Rec'd: _____

Entity: _____
 Doc Type: Report
 Doc Subtype: Lead Mapping
 Program: _____
 County: _____
 Secondary ID: OH 5003012

ack to EPA 585375


NORTH



SECOND FLOOR

- Compartment 3 - Resident Rooms
- Compartment 4 - Offices
- Compartment 5 - Bathrooms/Shower Rooms
- Compartment 6 - Dining Areas/Kitchens
- Compartment 9 - Lounges/Foyers
- Compartment 10 - Stairs
- Compartment 11 - Nurses Stations
- Compartment 12 - Laundry/Linens
- Compartment 13 - Storage/Supply Areas
- Other (Includes Utility rooms, Boiler Room, etc.)

- Smoke Detector - Wall Mounted
- ✕ Smoke Detector - On Ceiling
- ★ Pull Station
- Fire Extinguisher
- Light and Sound



NARRATIVE OF ST. MARY'S ALZHEIMER'S CENTER - PWS #5003012
LEAD MAPPING AND SAMPLE MONITORING POINTS - PLUMBING

Address:

1899 W. Garfield Street
Columbiana, Ohio 44408
330-549-9259

Administrator: Miriam Maughan

Maintenance Director: Steve Walker

St. Mary's Alzheimer's Center is a 110 bed, long term care skilled nursing facility. The facility has approximately 100 employees. The building was constructed and opened in 1987. It is a one story, wood constructed/brick veneer, shingle roof facility. The facility has full fire sprinkler protection throughout, with insulated and heated attic. There is an on-site commercial Kitchen and Laundry.

The Administrative offices are located in a two-story building with basement on the west side of the nursing facility. The building consists of concrete flooring and wall construction, and has full fire sprinkler protection throughout. No rooms in this building are occupied by residents.

St. Mary's does not receive its water from any municipality. The water source is obtained from an on-site well, and distributed throughout the facility after chlorination treatment. The wellhead is located in a concrete enclosure adjacent to the basement boiler room (location is depicted on page 2 of the treatment equipment schematic sheets enclosed).

The water service and distribution supply lines are copper. There are no lead service lines present in the facility. Water service line from the wellhead is 2" copper, continuing in to the water treatment equipment room where the service line is changed to NSF/PVC fittings and piping. Once the water has completed the cycle through the filtering and softening equipment, the service line then reverts back to copper fittings and supply distribution piping. The distribution piping is brought in to the nursing facility through the attic and continues down the center of the 1st floor corridors. Branch lines are tapped off the distribution piping and brought in overhead, dropping in to the interior walls leading to the plumbing fixtures in all locations.

All plumbing fixtures throughout the facility are commercial grade chrome-plated brass or metal fixtures (i.e., Symmons, Chicago, T&S Brass, etc.) Any potential lead content in the fixtures is unknown. No particular specification could be located or determined as to the type solder used in copper piping fittings and solder connections, but most likely to be either 50% tin and 50% lead, or 95% tin and 5% antimony.

02/04/2017

NARRATIVE OF ST. MARY'S ALZHEIMER'S CENTER
LEAD MAPPING AND SAMPLE MONITORING POINTS - PLUMBING (continued)

The sample point locations for obtaining lead and/or copper samples are as follows:

Room 1
Room 11
Room 17
Public Restroom (located on 1st floor of Administrative building off of foyer)
Employee Lounge
West Nourishment Room
Kitchen Prep Sink
Drinking Fountain (next to Electrical Room in Nursing Facility on 1st floor)
Room 203
Room 30

Please feel free to contact us if there are questions or additional information is required.

Steve Walker can be reached at (330)-549-9259 (facility number) or by cell phone at (330)-503-7642.

Paul R. Warren
Windsor House, Inc.
101 W. Liberty St.
Girard, Ohio 44420
PH: 330-545-1550 (ext. 9940)
FX: 330-545-2444
CL: 330-550-9331
pwarren@windsorhouseinc.com