




# Village of Doylestown Water System



## Legend

-  PB&CU Sample Sites
-  Water Distribution Lines
- \*No Lead Services\*



# The Village of Doylestown

**Matt Gaugler - Public Utilities  
Manager**



**A VILLAGE WITH VALUES**

**A TOWN OF TRADITIONS**

---

## No Lead Services Narrative

After reviewing documentation and interviewing water department staff, there is no evidence of any lead water service lines in the Village of Doylestown PWS distribution system(**PWS ID OH8500612**).

The Village of Doylestown is currently 5 years into a 10 year water meter replacement plan for all Village of Doylestown water customers. In the last 5 years the water department staff has replaced 627 water meters of the 1356 water services. The meter replacement process alone allowed the staff to get a hands on inspection of 46% of all water services. When taking into account all other work orders performed by the staff, an estimated 85% of all water services have been visually inspected and no lead services have been detected. The employees interviewed on the water department staff have a combined 50 years of service in the Village of Doylestown PWS.

The water department staff will continue to check the material of the remaining 50% of water services as the remaining water meters are replaced. In conclusion it is my opinion and consensus of the department staff that no lead services exist in the Village of Doylestown distribution system.

Matt Gaugler  
Public Utilities Manager  
Village of Doylestown  
24 S. Portage Street  
Doylestown, Ohio 44230  
W. 330-658-2181 ext.1141

Phone: 330-658-2181 ext. 1141

[www.doylestown.com](http://www.doylestown.com)

Fax:330-658-3838

*We Are An Equal Opportunity Provider and Employer*






## VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS CLAIMING NO LEAD SERVICE LINES

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):


<b>LEAD SERVICE LINE VERIFICATION</b>
<p><b>This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):</b></p> <p><input checked="" type="checkbox"/> Historical permit records and/or local ordinances</p> <p><input checked="" type="checkbox"/> Distribution maintenance records (i.e. meter replacement, waterline break repairs)</p> <p><input type="checkbox"/> Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)</p> <p><input type="checkbox"/> Service line material of all service lines is known (i.e. all service lines are known to be PVC)</p>

	3/3/17
Signature of Responsible Person	Date
Matt Gaugler      Public Utilities Manager	
Printed Name and Title of Responsible Person	

**PWS NAME:** Village of Doylestown  
**PWS ID:** OH8500612  
**COUNTY:** Wayne

<p><b><u>For Ohio EPA use only:</u></b></p> <p>Date Verification Rec'd: _____</p>
---

# Village of Doylestown Water System



Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

## Legend

- ★ PB&CU Sample Sites
- Water Distribution Lines
- \*No Lead Services\*