

RE: Club Island Association
Report
Drinking Water Program
Mercer County
PWS ID: OH5402012

Lead Mapping - Club Island Association Public Water System OH5402012 - 2017




Water Sampling Locations for Year-round Residents. All are SFH
 There are no Tier 1 sites. This development was started in 1952. It is primarily a summer, resort-type population.



Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

Club Island water mains are PVC. The public side service lines are Poly. There are 54 service connections.

Map legend, Private Side Identification, non-lead.



Our repair history has shown copper and poly water service lines from the curb to the homes on the public side.