

West Farmington Lead and Copper Map Key and Information

Our distribution system is made up of plastic (PVC) main lines and plastic service lines, with the exception of a few newer copper service lines that replaced broken older services. None of these should pose any threat as far as lead goes. Our finished water PH fluctuates from 7.7 to 8.1 throughout the year. This keeps us consistently on the light scaling side as well.

In an effort to create a more complete map we have sent out a notice to the consumers asking to notify us of their internal plumbing. The notices we delivered 2/17/17-2/18/17. As we gather information it will be recorded into an excel spreadsheet and the map updated for possible problem areas.

- Testing locations for Lead and Copper have been traced in **Blue** outlines.
- Any homes with internal plumbing that could pose a lead threat will be highlighted in **Pink**

ORC: Daniel Patchin II

Work:330-889-3336

Cell:330-553-4962

Owner/Mayor: Shirley McIntosh

Village Hall:330-889-2699

VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS CLAIMING NO LEAD SERVICE LINES

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

LEAD SERVICE LINE VERIFICATION

This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):

- ☐ Historical permit records and/or local ordinances
- ☐ Distribution maintenance records (i.e. meter replacement, waterline break repairs)
- ☐ Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)
- ☒ Service line material of all service lines is known (i.e. all service lines are known to be PVC)

Daniel Patchin II 2/28/17
Signature of Responsible Person Date
Daniel Patchin II ORC
Printed Name and Title of Responsible Person

PWS NAME: Village of West Farmington
PWS ID: OH7803911
COUNTY: Trumbull

For Ohio EPA use only:

Date Verification Rec'd: _____

West Farmington

