

RE: Plymouth Village
Report
Drinking Water Program
Richland County
PWS ID: OH7004003

To whom it may concern,

All of The Village of Plymouth's public service lines are known not to contain lead based on service, purchase and maintenance records. All of Plymouth's lines are transite, C-900 or C909 type water lines; the newest installed just 4 years ago.

Bill Hudson, Village Administrator

Village of Plymouth

2/17/2017

RECEIVED

MAR 02 2017

**OHIO E.P.A.
N.W.D.O.**


Village of Plymouth Water Distribution System - Lead Mapping



Legend

- Plymouth Corp Limits
- Existing Water Mains**
- 4"
- 6"
- 8"
- 12"
- No Lead -Structure Built After 1998
- Possible Lead -Structure Built in 1998 or Before
- No Structure

Note: All Public Service Lines are Non-Lead



Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.