RE:

Sacred Heart School Report Drinking Water Program Richland County PWS ID: OH7037812



D Well drilled in (2) Parish Cewber Built in the 1900's 3 SH Church Built in 1890 1) SH School Built in 1951

· No leard lines / N A Water lines are copper with lead solder.

Bathrooms locatedinthe Gym/ Hall - 1973 Parish Center - 1985 School - 1951 Church- 1992

RECEIVED

MAR 01 2017 DDAGW - NWDO

Lead Sample Sites Boy's bathroom sink 1 Boy's bathroom sink Z Girl's bathroom sink 1 Girl's battroom sink Z Kitchen Sink

VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS CLAIMING NO LEAD SERVICE LINES

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

LEAD SERVICE LINE VERIFICATION

This PWS states they have no lead service lines and has reviewed the following information (select one or more of the

☐ Historical permit records and/or local ordinances

following):

For Ohio EPA use only:

Lead wispping vermeadon rorm newsed 2/14/17

Date Verification Rec'd:

☐ Information pertaining to installation da (i.e. after 1986 when lead services lines ☒ Service line material of all service lines service lines are known to be PVC)	s were banned)
Signature of Responsible Person Date So Myors Principal Printed Name and Title of Responsible Person	PWS NAME: Sacred Heart? PWS ID: OH_OH 703781 2 COUNTY: Richland

MAR 01 2017 DDAGW - NWDO