

Please see supporting documents to find your street from the quadrants shown.

**Legend**

— Possibility of Lead Service Line

■ Building

**Lead Mapping Quadrants**

**Number**

1

2

3

4


5

6

7

Created: February 28, 2017  
Not To Scale

RECEIVED  
MAR 06 2017  
Central District Office  
Ohio EPA



# Village of Johnstown Water Map for Lead Services and Internal Plumbing

# Supporting Lead Map Documentation

Jim Lenner  
Village Manager

Jack Liggett  
Assistant  
Manager

Newt Long  
Service Director

Dana Steffan  
Finance Director



Sean Staneart  
Mayor

Council Members  
Ben Lee  
Sharon Hendren  
William Van  
Gundy  
Lewis Main  
Cheryl Robertson  
Carol Van Deest

599 South Main / P.O. Box 457  
Johnstown, OH 43031  
(740) 967-3177 tel. / (740) 967-3519 fax  
[www.johnstownohio.org](http://www.johnstownohio.org)

## Section 1

| Development                  | Phase              | As-Built date        |
|------------------------------|--------------------|----------------------|
| Concord Rd                   | 1 & 2              | 2015                 |
| Concord Crossing West        | 1<br>2<br>3 & 4    | 1992<br>1994<br>1995 |
| Concord Crossing East        | 1 & 2              | 2008                 |
| Villages at Concord Crossing | Entire development | 1998                 |
| Commerce Blvd                | Entire Rd          | 1996                 |
| Green Scape Ct.              | Entire Rd          | 1996                 |
| Phillips Dr.                 | Entire Rd          | 2006                 |

Per As-built maps, codified ordinances of the village and service records it appears that there are no lead service lines in this area.

All homes in this area are of a lower risk for lead in their internal plumbing expect for homes built before 1998. Homes that were built before may have a higher probability for lead in the internal plumbing of the house. These homes will most likely be found in the Concord Crossing West development, Commerce Blvd and, Green Scape Ct. The streets with homes that have a higher probability of lead in their internal plumbing have been denoted with blue text.

# Supporting Lead Map Documentation

## Section 2

| <b>Development</b> | <b>Phase</b> | <b>As-Built date</b> |
|--------------------|--------------|----------------------|
| Leafy Dell         | 1            | 1991                 |
| Leafy Dell         | 2            | 2002                 |
| Leafy Dell         | 3            | 2002                 |
| Leafy Dell         | 4            | 2004                 |
| Leafy Dell         | 5            | 2005                 |
| Leafy Dell         | 6            | 2014                 |
| Leafy Dell         | Condos       | 2004                 |
| Leafy Dell         | Apartments   | 2002                 |

Per As-built maps, codified ordinances of the village and service records it appears that there are no lead service lines in this area.

All homes in this area are of a lower risk for lead in their internal plumbing expect for homes built before 1998. Homes that were built before may have a higher probability for lead in the internal plumbing of the house. These homes will be found in the Leafy Dell development phase 1 which includes the following streets: Leafy Dell Rd., Stonehenge Dr., Grassy Knoll Way, Leafy Knoll Way, Pepperwood Place, Sassafra Place and, Greenstick Way. The streets with homes that have a higher probability of lead in their internal plumbing have been denoted with blue text.

# Supporting Lead Map Documentation

## Section 3

| Development  | Phase          | As-Built date     |
|--------------|----------------|-------------------|
| Jersey St    | West<br>East   | 2016<br>1991      |
| Williams St  | South<br>North | 1978<br>C900      |
| Oregon St    | South<br>North | 1978<br>Unknown   |
| Main St      | South<br>North | 2011<br>2010-2016 |
| Kasson St    | South<br>North | 1991<br>C900      |
| Douglas St   | West<br>East   | 1992<br>1988      |
| Track St     | Entire Rd.     | 2001              |
| Pratt St     | West<br>East   | Unknown<br>2007   |
| Phalen St    | Entire Rd.     | K copper          |
| Locker St    | Entire Rd.     | 2000              |
| Payne        | Entire Rd.     | 1987              |
| Maple St     | East           | 2000              |
| Stevens St.  | Entire Rd.     | 2000              |
| Anna way St. | Entire Rd.     | 1994              |
| Rice St      | Entire Rd.     | 1987              |
| Elm St       | Entire Rd.     | 1987              |
| Yardner St   | Entire Rd.     | 2007              |
| Ford Ave     | Entire Rd.     | 2007              |

## Supporting Lead Map Documentation

|                |                    |            |
|----------------|--------------------|------------|
| Briarwood Apt. | Entire Development | 1973       |
| Chimes Terrace | Entire Development | 2011       |
| Liberty St     | Entire Rd.         | Unknown    |
| McCracken Dr.  | Entire Rd.         | Unknown    |
| Fairview Dr.   | Entire Rd.         | 2005       |
| Drury Ln       | Entire Rd.         | 2005       |
| Recreation Dr. | Entire Rd.         | Galvanized |
| Upham Rd       | Entire Rd.         | Unknown    |
| Pershing Dr.   | Entire Rd.         | Unknown    |
| Edwards Rd     | Entire Rd.         | 2005       |

Per As-built maps, codified ordinances of the village and service records it appears that there is a possibility of lead services lines on the following streets: Pershing Dr., Upham Rd., McCracken Dr., Liberty St, W. Pratt and, N. Oregon St. The rest of the streets in this area appears to have no lead service lines.

All homes in this area are of a higher probability for lead in the internal plumbing of the house. The streets with homes that have a higher probability of lead in their internal plumbing have been denoted with blue text.

# Supporting Lead Map Documentation

## Section 4

### Development

Rolling Meadows

### Phase/Rd

Valley View  
Saratoga  
Meadow

### As-Built date

1957  
1957  
1957

Sunset

1958

Hillview

1958

Ridgeview

1958

Crestview

1958

Parkside

1958

Park Lane

1958

Northview

1958

Lakeview

1958

Lewis

1961

Hunts worth

1961

Westview

1961

Per As-built maps, codified ordinances of the village and service records it appears that there are no lead service lines in this area.

All homes in this area are of a higher probability for lead in the internal plumbing of the house. The streets with homes that have a higher probability of lead in their internal plumbing have been denoted with blue text.

# Supporting Lead Map Documentation

## Section 5

| <b>Development</b> | <b>Phase</b>             | <b>As-Built date</b> |
|--------------------|--------------------------|----------------------|
| Raccoon Creek      | Entire Development       | 2008                 |
| W. Coshocton St.   | Meadow Ln.- Westview St. | 1982                 |

Per As-built maps, codified ordinances of the village and service records it appears that there are no lead service lines in this area.

All homes in this area are of a lower risk for lead in their internal plumbing expect for homes built before 1998. Homes that were built before may have a higher probability for lead in the internal plumbing of the house. These homes will most likely be found on W. Coshocton St. The streets with homes that have a higher probability of lead in their internal plumbing have been denoted with blue text.

## Supporting Lead Map Documentation

### Section 6

| <b>Development</b> | <b>Phase</b>       | <b>As-Built date</b> |
|--------------------|--------------------|----------------------|
| Kyber Run          | 1 & 2              | 1999                 |
| Greens of Kyber    | Entire Development | 2013                 |

Per As-built maps, codified ordinances of the village and service records it appears that there are no lead service lines in this area.

All homes in this area are of a lower risk for lead in their internal plumbing expect for homes built before 1998. Homes that were built before may have a higher probability for lead in the internal plumbing of the house. There appears to be no that have a higher probability for internal lead plumbing in this area.



# Supporting Lead Map Documentation

## Section 7

| Development      | Phase                     | As-Built date |
|------------------|---------------------------|---------------|
| Clark Dr.        | 1                         | 2001          |
|                  | 2                         | 2002          |
|                  | 3                         | 2010          |
| Cherry Hill Rd   | Entire Rd                 | 1994          |
| Old Kroger Plaza | Entire development        | 1993          |
| W. Coshocton St. | Westview St. – Corp Limit | 1988          |

Per As-built maps, codified ordinances of the village and service records it appears that there are no lead service lines in this area.

All homes in this area are of a lower risk for lead in their internal plumbing expect for homes built before 1998. Homes that were built before may have a higher probability for lead in the internal plumbing of the house. These homes will most likely be found on Cherry Hill Rd, W. Coshocton St. and, Kroger Plaza. The streets with homes that have a higher probability of lead in their internal plumbing have been denoted with blue text.

411

April 25  
1965

ORDINANCE NO. 411

ORDINANCE NO. 412

REGULATING MINIMUM REQUIREMENTS FOR ACCEPTANCE OF ROADS AND STREETS WITHIN THE VILLAGE OF JOHNSTOWN, OHIO.

BE IT ORDAINED BY THE COUNCIL OF THE VILLAGE OF JOHNSTOWN, OHIO, three-fourths (3/4ths) of all members elected thereto concurring:

Section 1. That on and after the effective date of this ordinance, no street or roadway within the Village of Johnstown, Ohio, shall be accepted or made a part of the Village Street System, unless and until the following improvements have been installed by the developer:

1. Four (4 inch) Amended to (6 inch) water main and copper service connection, complete with curb box.
2. Where Sewer for sanitary purpose is available, sanitary sewer of a minimum capacity of eight (8") inches, and sewer laterals of a minimum capacity of six (6") inches.
3. Said street is brought down to permanent grade.
4. Said street is paved with a nine (9") inch base of water bound macadam bond and seal-cote top.
5. Installation of concrete curb, minimum size of 6" x 9" x 18" on 4" of ash bond.
6. Contractor shall provide storm sewers or proper draining ditches to conform with Council specifications.
7. No street shall be accepted into the Village system having a pavement width of less than twenty-four (24') feet.
8. No street shall have a dedicated width of less than thirty-three (33') feet.
9. That any developer planning to have a street, Council streets or roadway accepted by Johnstown Village Council, shall first have plans prepared by a registered engineer, which plans shall be submitted to the Johnstown Village council.
10. Said streets are to be constructed by an accredited and reliable contractor. During the course of construction of any streets, sewers or water mains, same shall be periodically inspected by Johnstown Village and the expense of the inspection shall be borne by the developer.
11. Any contractor developer constructing streets, sewers or water lines within the Village of Johnstown, Ohio, shall be required to post a maintenance bond or its equivalent for one year maintenance and said maintenance bond shall be not less than ten (10%) per cent of the cost of said construction.

411

ORDINANCE NO. 411

Page - 2 -  
Ordinance No. 412

12. Fire-hydrant's shall be installed no less than 10000 (Amended to 1,000 feet) feet apart, said Hydrant to be approved by the Johnstown Village Fire Chief.

Section 2. The foregoing ordinance is hereby declared to be an emergency measure, for the emergency being the necessity to provide for a uniform standard for any streets within the Village of Johnstown, Ohio.

Section 3. Ordinances or parts of ordinances in conflict herewith are hereby repealed.

passed in Council this 1 st. day of April 1957.

Approved: Edgar Lewis  
Mayor

Attested: Marjorie Drake  
Clerk

payment of an amount equal to the minimum monthly charge for each month of the intervening period, but not to exceed twelve (12) months.

Entity: Johnstown  
Doc Type: Report  
Doc Subtype: —  
Program: Drinking Water  
County: Licking  
Secondary ID: OH4501512

Rec 'd: 3/6/17