

RE: Carey Village PWS
Report
Drinking Water Program
Wyandot County
PWS ID: OH8800012

PWS ID #: OH8800012

Narrative for Lead for the Village of Carey, Ohio

RECEIVED
MAR 06 2017

OHIO E.P.A.
N.W.D. Unit

All water mains in the village of Carey are cast iron, ductile iron, transite, or PVC per original as-built drawings of old water tower and first original water mains from 1894 on. They are depicted on the map in red.

We believe the village had ceased installing lead service lines prior to 1950. Any and all lead lines found are and have been replaced when discovered since 1980.

All of the village streets are labeled in black bold lettering.

Research of village sub division formation dates revealed approximate date of water main and service line installation as well as home and building construction dates.

The map has the background of the different areas shaded to depict dates of installation.

Yellow background shade: Areas constructed pre 1998

Blue background shade: Areas constructed between 1998 and 2014

Green background shade: Areas constructed in 2014 and after

The yellow shaded areas contain sections that are likely to have lead service lines.

The blue shaded areas contain no lead service lines but buildings within may have plumbing materials or solder containing 8% or less lead by weight.

The green shaded areas contain no lead service lines and buildings within have plumbing materials or solder containing .25% or less lead by weight.

A copy of our Lead and Copper sample monitoring point ID's (SMP ID) is also included with this map.

