



Winding Creek Estates

Fallsburg Rd NE

El Rancho Dr NE

WELL

MAIN LINE IS STEEL AND ALL SERVICES ARE PLASTIC

WINDING CREEK ESTATES
OH4300512
FACILITY DS1
● PLASTIC SERVICES
— STEEL WATER MAINS

280
290
LC201

270
LC203

260

250

240

230
LC204

220

210

200
LC202

10

30

40

20

60

80

70

50

100

110

LC205

90

© 2016 Google

Google Earth


2004

Imagery Date: 9/23/2014 40°07'24.95" N 82°20'51.48" W elev 901 ft eye alt 1474 ft

Winding Creek Estates Lead and Copper Mapping Required Narrative

Winding Creek Estates MHP consists of mobile homes. The MHP water distribution system is comprised of steel and plastic/PVC. The attached map is prepared with information provided from past owners of the park as well distribution maintenance.

I further recognize the Ohio EPA's statement that the characteristics of buildings and piping solder or fixtures would be buildings built prior to 1998 or that use of plumbing material or solder manufacture before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition buildings built and plumbing materials manufactured after 2014 were required to have less than .25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however, that although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective. For the instances listed, the park's owner has no control. All Lead testing to date has been determined to be below detection levels.

 _____, Owner