Tri County Rural Water and Sewer Association

Lead Service Mapping Narrative

Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

Tri County Rural Water and Sewer Association started distribution in 1994. We use multiple line sizes and types to deliver water to our customers.


Tri County Rural Water and Sewer Association water main lines consist of 10% Ductile iron, 90% PVC and HDPE {High Density Poly Ethylene}. No materials that we install on our water mains contain lead. Tri County Rural Water and Sewer Association's service lines from meter set to individual household is at customer discretion.

Tri County Rural Water and Sewer Association tests for lead and copper in the water from Tier 1 houses that are dwellings built before 1986 that would have the best chance to have any plumbing and fixtures with lead content. Test sites vary due to the age and geographic area of our water distribution system. Tri County Rural Water and Sewer Association is currently and has for many years treated our water distribution system with Phosphate as a prevention to coat the lines from lead absorption into the water. We sample according to the EPA regulations and all sample results return within guidelines. The results of these tests are available by requesting a Consumer Confidence Report from Tri County Rural Water and Sewer Association Office.

To find out the age of the customers home tax maps as a reference for when the dwelling was built can be found at your local county office in which the dwelling is located. Of the houses constructed prior to the 1998 low lead law was put into place may have solder and fixtures that contain lead. Tri County Rural Water after the 1998 law is unsure at the amount of homes that may contain lead or solder. Tri County Rural Water has no jurisdiction over interior plumbing but wants to inform them of the possibility of lead dangers but we cannot enforce them to change their interior plumbing.

Tri County Rural Water and Sewer Association is not responsible for the customers water lines from the shut off to the inside of the home.


Tri-County Rural Water System Inventory



Miles

GIS Specialist at Buckeye Hills http://www.buckeyehills.org | 740.374.9436

Page 1 of 110



Page 2 of 110



Page 3 of 110



Page 4 of 110



Page 5 of 110



Page 6 of 110



Page 7 of 110



Page 8 of 110



Page 9 of 110




Page 10 of 110



Page 11 of 110



Page 12 of 110




Page 13 of 110



Page 14 of 110



Page 15 of 110



Page 16 of 110



Page 17 of 110



Page 18 of 110



Page 19 of 110



Page 20 of 110




Page 21 of 110



Page 22 of 110




Page 23 of 110



Page 24 of 110



Page 25 of 110



Page 26 of 110



Page 27 of 110



Page 28 of 110



Page 29 of 110



Page 30 of 110



Page 31 of 110



Page 32 of 110



Page 33 of 110



Page 34 of 110



Page 35 of 110



Page 36 of 110



Page 37 of 110



Page 38 of 110



Page 39 of 110



Page 40 of 110



Page 41 of 110



Page 42 of 110



Page 43 of 110




Page 44 of 110




Page 45 of 110




Page 46 of 110



Page 47 of 110



Page 48 of 110



Page 49 of 110



Page 50 of 110



Page 51 of 110



Page 52 of 110




Page 53 of 110



Page 54 of 110




Page 55 of 110



Page 56 of 110



Page 57 of 110



Page 58 of 110



Page 59 of 110



Page 60 of 110



Page 61 of 110



Page 62 of 110



Page 63 of 110




Page 64 of 110



Page 65 of 110



Page 66 of 110



Page 67 of 110



Page 68 of 110



Page 69 of 110



Page 70 of 110



Page 71 of 110



Page 72 of 110



Page 73 of 110




Page 74 of 110



Page 75 of 110



Page 76 of 110



Page 77 of 110




Page 78 of 110



Page 79 of 110



Page 80 of 110



Page 81 of 110



Page 82 of 110



Page 83 of 110



Page 84 of 110



Page 85 of 110



Page 86 of 110



Page 87 of 110



Page 88 of 110




Page 89 of 110



Page 90 of 110



Page 91 of 110



Page 92 of 110



Page 93 of 110



Page 94 of 110



Page 95 of 110



Page 96 of 110




Page 97 of 110



Page 98 of 110



Page 99 of 110



Page 100 of 110



Page 101 of 110



Page 102 of 110



Page 103 of 110



Page 104 of 110



Page 105 of 110



Page 106 of 110



Page 107 of 110



Page 108 of 110



Page 109 of 110



Page 110 of 110

