

Jefferson Lodge Mobile Home Park

PWS ID #: OH4900612

● = Non - Lead

● = Lead

● = No Information

— = Water lines which may contain Lead



Jefferson Lodge Copper and Lead Map

PWS ID # OH4900612

Each home within the park is fed with polyethylene pipes. Anything inside the home is the resident's responsibility. Each home is fed with either polyethylene or copper mechanical fixtures and pipe.

The Maintenance garage also holds the well house. The wells and the well house use either galvanized steel or schedule 40 polyethylene pipe and fixtures.

The unused office building is designated "Unknown" because the building has been empty and is slated to be demolished sometime in the future. No information regarding the pipes, fixtures or any other water related items is available.

Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

**VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS
CLAIMING NO LEAD SERVICE LINES**

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all service lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

LEAD SERVICE LINE VERIFICATION
<p>This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):</p> <ul style="list-style-type: none"><input type="checkbox"/> Historical permit records and/or local ordinances<input checked="" type="checkbox"/> Distribution maintenance records (i.e. meter replacement, waterline break repairs)<input type="checkbox"/> Information pertaining to installation dates for all service lines (i.e. after 1986 when lead service lines were banned)<input type="checkbox"/> Service line material of all service lines is known (i.e. all service lines are known to be PVC)

Jessie Ward 3/8/17
Signature of Responsible Person Date

Jessie Ward
Printed Name and Title of Responsible Person

PWS NAME: JEFFERSON LODGE
PWS ID: OH 4900612
COUNTY: MADISON

<p>For Ohio EPA use only:</p> <p>Date Verification Rec'd: <u>KAA</u> 3/09/17</p>
