


## MONTGOMERY COUNTY, OHIO



# OFFICIAL WATER ATLAS



City of Brookville  
PWS ID: OH5700203  
The Brookville water system is made up of 4" -12" water main, a mixture of cast iron and ductile iron pipe. There are no plastic mains in the system. While there is potential for lead service lines in areas built prior to 1970, there are none that are known.

Built prior to 1949. Highly probable that lead-containing materials exist in the plumbing system

Built in 1950-1969. Highly probable that lead-containing materials exist in the plumbing system.

Built 1970-1989. Probable that lead-containing materials exist in the plumbing system.

Built 1990-present. Less probable that lead-containing materials exist in the plumbing system, although potential still exists. Many of the materials were reducing lead content, with eventual removal in 2014.

Buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2010 were required to have less than 0.2% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.