

# Village of Waynesburg

## PWS# OH7605712

The Village has no known lead service lines.

Village is 92% Residential users.

99% of all water mains were replaced in 1993.



### LEGEND



Areas that contain buildings built prior to 1998 that may contain copper with lead solder or fixtures that contain lead.



Areas with lead service lines, N/A, NONE KNOWN.



Pocket of homes built after 1998