

VALLEY MOBILE HOME PARK
OH4503112
FACILITY ID- DS1

- PLASTIC SERVICES
- STEEL SERVICE LINE

WELL HOUSE

LC201

LC205

Valley Mobile Home Court

LC202

LC203

LC204

T.J. Evans Panhandle Recreational Trail

© 2016 Google

Google Earth

2004

Imagery Date: 9/23/2014 40°04'37.01" N 82°16'11.71" W elev 804 ft eye alt 2347 ft


**VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS
CLAIMING NO LEAD SERVICE LINES**

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all service lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

LEAD SERVICE LINE VERIFICATION
<p>This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):</p> <ul style="list-style-type: none"> <input type="checkbox"/> Historical permit records and/or local ordinances <input type="checkbox"/> Distribution maintenance records (i.e. meter replacement, waterline break repairs) <input type="checkbox"/> Information pertaining to installation dates for all service lines (i.e. after 1986 when lead service lines were banned) <input checked="" type="checkbox"/> Service line material of all service lines is known (i.e. all service lines are known to be PVC)


Signature of Responsible Person 2-25-2017 Date
Phil Caselutz Owner
Printed Name and Title of Responsible Person


PWS NAME: Valley Mobile Home Park 2503112
PWS ID: OH 4503112
COUNTY: Licking

<p>For Ohio EPA use only: Date Verification Rec'd: _____</p>
--

Valley Mobile Home Park Lead and Copper Mapping Required Narrative

Valley MHP consists of mobile homes. The MHP water distribution system is comprised of plastic/PVC. The attached map is prepared with information provided from past owners of the park as well distribution maintenance.

I further recognize the Ohio EPA's statement that the characteristics of buildings and piping solder or fixtures would be buildings built prior to 1998 or that use of plumbing material or solder manufacture before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition buildings built and plumbing materials manufactured after 2014 were required to have less than .25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however, that although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective. For the instances listed, the park's owner has no control. All Lead testing to date has been determined to be below detection levels.

 Owner

Phil Coblenz