

Pheasant Run Association PWS ID: OH4701912
 200 Eastlake Dr/LaGrange OH 44050/440-355-5011

Green = Non-Lead Main Water Line

Pheasant Run Association

200 Eastlake Dr

LaGrange OH 44050


440-355-5011

PWS ID: OH4701912

Lead Mapping in Distribution Systems: Narrative Description

It is our belief that we have no buildings containing lead solder, plumbing or fixtures.

Because it is practically impossible to determine the lead content of an installed fixture, fitting or pipe, it should be assumed that the manufacture or installation date is the primary indicator of the lead content. Therefore, the characteristics of buildings and piping solder or fixtures would be buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998 may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, buildings built and plumbing materials manufactured after 2014 were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.



Glenn Miller, Board President

3-9-17