

VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS CLAIMING NO LEAD SERVICE LINES

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

LEAD SERVICE LINE VERIFICATION
This PWS states they have no lead service lines and has reviewed the following information (select one or more of the following):
<input type="checkbox"/> Historical permit records and/or local ordinances
<input checked="" type="checkbox"/> Distribution maintenance records (i.e. meter replacement, waterline break repairs)
<input type="checkbox"/> Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)
<input type="checkbox"/> Service line material of all service lines is known (i.e. all service lines are known to be PVC)

Tony DeLuke 5/22/17
Signature of Responsible Person Date

TONY DeLuke
Printed Name and Title of Responsible Person

PWS NAME: Western Reserve
PWS ID: OH 7704012
COUNTY: Summit

For Ohio EPA use only
Date Verification Rec'd: <u>MAY 22 2017</u>

BY:

Lead Mapping Verification Form Revised 2/14/17

Entity: _____
Doc Type: Report
Doc Subtype: Lead mapping
Program: SDAW
County: Summit
Secondary ID: OH 7704012
add to eDRC 585661

Monday, May 22, 2017

Western Reserve Village

PWS ID: OH7704012

Because it is practically impossible to determine the lead content of an installed fixture, fitting or pipe, it should be assumed that the manufacture or installation date is the primary indicator of the lead content. Therefore, the characteristics of buildings and piping solder or fixtures would be **buildings in Ohio built prior to 1998 or that use plumbing material or solder manufactured before 1998** may have materials with greater than 8% lead and are at a higher risk of contributing lead to the drinking water than materials manufactured after 1998. In addition, **buildings built and plumbing materials manufactured after 2014** were required to have less than 0.25% lead by weight and have the lowest risk for contributing lead to the drinking water. It should be noted however that, although prohibited, some use of leaded solder or leaded components may have occurred after the prohibitions became effective.

Western Reserve



LC205
132 130 128 126 124 122 120 118 116 114 112 110 108 106 104 102 100

Maple Hill Lane
133 131 129 127 125 123 121 119 117 115 113 111 109 107 105 103 101

LC201
44 42 40 38 36 34 32 30 28 26 24 22 20 18 16 14 13 12

Shady Acres Drive
41 39 37 35 33 31 29 73 25 23 21 19 17 15
59 62 64 66 68 70 72 75 77 79 81 83 85
Shady Acres Drive

Pump House

58 60 61 63 65 67 69 71 74 76 78 80 82 84 86 88 90

A
L
B
R
E
C
H
T