Village of Glenmont

108 Main St. P.O. Box 476

Glenmont, oh 44628

330-377-4179

**Glenmont Water Works** 


Re: No Lead Service Lines PWS ID. OH3800312

Mr. Bewley

The Village of Glenmont has **no lead main service lines** in the Village. As stated in the mapping we showed the lines were transite and C900 Plastic. As far as the village and plant operator knows, all lines from the Village curb stops to the residence are Copper, Plastic, or Galvanize. It has always been the land owner's responsibility to supply the water line from the curb stop on the main line to their residence. It is not the village's responsibility to maintain or replace any lines from the curb stop to the home or inside the home.

If you have more questions, feel free to call me at (330) 231-0512 Lester Gray Glenmont Water Works Operator WS1-1102241-07 PWS ID. OH 3800312

Village of Glenmont P.O. Box 476 Glenmont, Oh. 44628



## VERIFICATION FORM FOR COMMUNITY PUBLIC WATER SYSTEMS CLAIMING NO LEAD SERVICE LINES

The owner or operator of all community public water systems must identify and map areas of their distribution system that are known or are likely to contain lead service lines. Systems must submit a copy of the applicable map to the Ohio Department of Health and the Ohio Department of Job and Family Services. Systems must also submit a report to the director containing at least both of the following: (1) The applicable map with narrative, and (2) A list of sampling locations used to collect samples as required by Ohio Revised Code (ORC) Section 6109.121 and any rules adopted thereunder, including contact information for the owner and occupant of each sampling site.

Should a water system determine no lead service lines exist in their distribution system, they must provide information stating they reviewed, at the minimum, historical permit records and local ordinances, distribution maintenance records and information pertaining to installation dates or materials for all services lines. This information must be verified below.

## I HEREBY CERTIFY THAT THE FOLLOWING METHOD(S) WERE USED TO DETERMINE NO LEAD SERVICE LINES EXIST IN THIS WATER SYSTEM'S DISTRIBUTION SYSTEM, AS REQUIRED BY ORC 6109.121(F):

∕ie∖	PWS states they have no lead service lines and has ved the following information (select one or more of the /ing):
	Historical permit records and/or local ordinances
Ø	Distribution maintenance records (i.e. meter replacement, waterline break repairs)
8	Information pertaining to installation dates for all service lines (i.e. after 1986 when lead services lines were banned)
	Service line material of all service lines is known (i.e. all service lines are known to be PVC)

Signature of Responsible Person Date LESTER GRAY WATER PLANT ODERATOR

PWS NAME: <u>GleNMONT WATER Work</u> PWS ID: OH <u>3800312</u> COUNTY: <u>Holmes</u>

Printed Name and Title of Responsible Person

For Ohio EPA use only:	<b>N</b>	<u>B</u>	Ø	TO:		V	B	
Date Verification Rec <sup>i</sup> d:		A	98	şa <b>n</b> ek	РУ Ij	<u>2ñ</u>		W

Lead Mapping Verification Form Revied 2/14/17.....

